





#### WDMA / AAMA / CSA JOINT TECHNICAL INTERPRETATION

### **REQUEST**

INTERPRETATION NUMBER

07-03

**DATE OF INQUIRY:** July 12, 2007

Approved 3/08

## PERTINENT JOINT WDMA/AAMA/CSA SPECIFICATION(S):

AAMA/WDMA/CSA 101/I.S.2/A440-05

# **SECTION(S) IN QUESTION:**

Section 5.3.6.4.2 Sash/leaf torsion test

## **INTERPRETATION REQUESTED:**

On Table 8, it shows that a dual-action window that desires a commercial rating does not need to receive the sash/torsion test, but on Table 25, it shows a dot for the sash/torsion to be performed.

1.) Since AAMA/NWWDA 101/I.S.2-97 and 101/I.S.2/NAFS-02 both indicated that the unglazed ventilator torsion test only applied to HC and AW classifications of Dual Action windows, is Table 25 of AAMA/WDMA/CSA 101/I.S.2/A440-05 incorrect in identifying that the Sash/leaf torsion test is a requirement of DAW-C products.

### **SUGGESTED INTERPRETATION:**

1.) Yes

## **REVIEW/APPROVED BY:**

COMMITTEE	COMMENTS / ACTION	STATUS	DATE
JDMG			
AAMA		Approved	2/27/08
CSA		Approved	10/10/07
WDMA		Approved	03/18/08